

Inspection Information

Inspection Date: 2025-12-06

Client Name: Larry Murbles

Client Address: unknown

Make: Aston Martin

VIN: SCFEABAK5DGC17432

Engine: 8 cylinder

Inspector Phone: unknown

Exterior Color: Mauve

Inspection Cost: unknown

Client Phone: unknown

Seller: unknown

Model: V8 Vantage

Body Style: Hatchback

Drive Type:
Inspector Email: unknown

Inspection Location: unknown

Client Email: unknown

Year: 2013

Mileage: 67781

Transmission: Manual

Inspector: Anju Chauhan

Interior Color: Camo

G = Good - This item is in good condition and/or is performing to standard.

F = Fair - This item is in fair condition and/or is performing adequately.

P = Poor - This item is in poor condition and/or is performing below standard.

Interior

G	F	P	
☒	☐	☐	1. Fuel Door Release
☒	☐	☐	2. Hood Release
☒	☐	☐	3. Trunk Lid Release
☒	☐	☐	4. Air Bags
☐	☐	☒	5. Tilt/Telescoping Steering Wheel - Suspendisse scelerisque velit ac ligula gravida, ac interdum nisi vehicula.
☒	☐	☐	6. Steering Wheel Controls
☐	☒	☐	7. Horn - Not functional
☒	☐	☐	8. Windshield Wiper Operation/Controls
☒	☐	☐	9. Windshield Washer Operation/Controls
☒	☐	☐	10. Instrument Panel
☒	☐	☐	11. Warning Lights
☐	☒	☐	12. Warning Chimes - Not functional
☒	☐	☐	13. Air Conditioning
☒	☐	☐	14. Heating System
☒	☐	☐	15. Defogger/Defroster
☒	☐	☐	16. Clock
☒	☐	☐	17. Radio

- | | | | |
|-------------------------------------|-------------------------------------|-------------------------------------|---|
| ☒ | ☐ | ☐ | 18. Audio Player |
| ☒ | ☐ | ☐ | 19. Speakers |
| ☐ | ☒ | ☐ | 20. Antenna - Not functional |
| ☐ | ☐ | ☒ | 21. Lighter/Power Outlet(s) - Not functional |
| ☒ | ☐ | ☐ | 22. Interior Courtesy/Map/Dome Light |
| ☒ | ☐ | ☐ | 23. Glove Box |
| ☒ | ☐ | ☐ | 24. Glove Box Light |
| ☐ | ☒ | ☐ | 25. Center Console - Loose |
| ☒ | ☐ | ☐ | 26. Sun Visors |
| ☒ | ☐ | ☐ | 27. Sun Visors Lights |
| ☒ | ☐ | ☐ | 28. Vanity Mirrors |
| ☒ | ☐ | ☐ | 29. Inside Rear View Mirror |
| ☒ | ☐ | ☐ | 30. Armrests |
| ☐ | ☒ | ☐ | 31. Outside Mirror Operation/Controls - Controls broken |
| ☐ | ☒ | ☐ | 32. Door Locks Manual - Will not lock |
| ☒ | ☐ | ☐ | 33. Door Locks Automatic |
| ☒ | ☐ | ☐ | 34. Child Safety Locks |
| ☒ | ☐ | ☐ | 35. Window Controls |
| ☒ | ☐ | ☐ | 36. Door Handles |
| ☒ | ☐ | ☐ | 37. Heated/Cooled Seats |
| ☒ | ☐ | ☐ | 38. Seats |
| ☒ | ☐ | ☐ | 39. Seat Controls |
| ☒ | ☐ | ☐ | 40. Headrest |
| ☒ | ☐ | ☐ | 41. Seat Belts |
| ☒ | ☐ | ☐ | 42. Sunroof/Moonroof |
| ☒ | ☐ | ☐ | 43. Convertible Top |
| ☒ | ☐ | ☐ | 44. Headliner |
| ☒ | ☐ | ☐ | 45. Carpet |
| ☐ | ☒ | ☐ | 46. Floor Mats - Loose or torn |
| ☒ | ☐ | ☐ | 47. Interior Trim |
| ☐ | ☒ | ☐ | 48. Door Panels - Scratched |

- | | | | |
|-------------------------------------|-------------------------------------|--------------------------|-----------------------------------|
| ☒ | ☐ | ☐ | 49. Luggage Compartment |
| ☐ | ☒ | ☐ | 50. Luggage Compartment Carpet |
| ☒ | ☐ | ☐ | 51. Luggage Compartment Cargo Net |
| ☒ | ☐ | ☐ | 52. Trunk Light |
| ☒ | ☐ | ☐ | 53. Jack and Tool Kit |

Exterior

- | G | F | P | |
|-------------------------------------|-------------------------------------|-------------------------------------|---|
| ☒ | ☐ | ☐ | 54. Windshield |
| ☒ | ☐ | ☐ | 55. Wiper Blades |
| ☒ | ☐ | ☐ | 56. Windows |
| ☒ | ☐ | ☐ | 57. Rear Window |
| ☒ | ☐ | ☐ | 58. Mirrors |
| ☒ | ☐ | ☐ | 59. Head Lights |
| ☒ | ☐ | ☐ | 60. High Beams |
| ☐ | ☐ | ☒ | 61. Parking Lights - Broken lens |
| ☒ | ☐ | ☐ | 62. Turn Signals |
| ☐ | ☒ | ☐ | 63. Taillights - Broken lens |
| ☒ | ☐ | ☐ | 64. Brake Lights |
| ☒ | ☐ | ☐ | 65. Hazards |
| ☒ | ☐ | ☐ | 66. License Plate Lights |
| ☐ | ☒ | ☐ | 67. Reverse Lights - Not functional |
| ☒ | ☐ | ☐ | 68. Fog Lights |
| ☒ | ☐ | ☐ | 69. Running Lights |
| ☒ | ☐ | ☐ | 70. Side Marker Lights |
| ☐ | ☒ | ☐ | 71. Body Panels - Corrosion or rust present |
| ☒ | ☐ | ☐ | 72. Front Bumper |
| ☒ | ☐ | ☐ | 73. Grille |
| ☒ | ☐ | ☐ | 74. Hood |
| ☒ | ☐ | ☐ | 75. Rear Bumper |
| ☒ | ☐ | ☐ | 76. Rear Hatch |

- | | | | |
|-------------------------------------|-------------------------------------|--------------------------|--|
| ☒ | ☐ | ☐ | 77. Trunk |
| ☒ | ☐ | ☐ | 78. Left Front Fender |
| ☒ | ☐ | ☐ | 79. Left Front Door |
| ☒ | ☐ | ☐ | 80. Left Rear Fender |
| ☒ | ☐ | ☐ | 81. Left Rear Door |
| ☒ | ☐ | ☐ | 82. Right Rear Fender |
| ☐ | ☒ | ☐ | 83. Right Rear Door - Paint chipped, faded or mismatched |
| ☒ | ☐ | ☐ | 84. Right Front Fender |
| ☒ | ☐ | ☐ | 85. Right Front Door |
| ☒ | ☐ | ☐ | 86. Roof |
| ☒ | ☐ | ☐ | 87. Roof Rack |
| ☒ | ☐ | ☐ | 88. Trim |
| ☒ | ☐ | ☐ | 89. Fuel Door |
| ☒ | ☐ | ☐ | 90. Paint |

Tires

- | | | | |
|-------------------------------------|-------------------------------------|--------------------------|-------------------------------------|
| G | F | P | |
| ☒ | ☐ | ☐ | 91. Tire Manufacturer/Brand |
| ☒ | ☐ | ☐ | 92. Alignment |
| ☒ | ☐ | ☐ | 93. Left Front Tire |
| ☒ | ☐ | ☐ | 94. Left Rear Tire |
| ☒ | ☐ | ☐ | 95. Right Rear Tire |
| ☐ | ☒ | ☐ | 96. Right Front Tire - Low pressure |
| ☒ | ☐ | ☐ | 97. Spare Tire |
| ☒ | ☐ | ☐ | 98. Wheels |
| ☐ | ☒ | ☐ | 99. Wheel Lug Nuts - Missing |

Underbody

G	F	P	
☒	☐	☐	100. Frame
☐	☐	☒	101. Overall Underbody Condition - Rust present
☒	☐	☐	102. Exhaust System
☐	☐	☒	103. Catalytic Converter
☒	☐	☐	104. Transmission Mounts
☒	☐	☐	105. Transmission
☒	☐	☐	106. Differential/Drive Axle
☒	☐	☐	107. Universal Joints/CV Joints/Boots
☒	☐	☐	108. Power Steering
☐	☒	☐	109. Suspension - Worn bearing plate
☒	☐	☐	110. Tie-Rods/Idler Arm
☐	☒	☐	111. Sway Bars
☒	☐	☐	112. Springs
☒	☐	☐	113. Shocks
☒	☐	☐	114. Control Arms
☒	☐	☐	115. Ball Joints/Bushings
☐	☐	☒	116. Rotors/Drums
☒	☐	☐	117. Calipers
☒	☐	☐	118. Parking Brake
☒	☐	☐	119. Brake Pads
☐	☒	☐	120. Brake Lines/Hoses/Fittings - Worn or damaged
☒	☐	☐	121. Brake Master Cylinder

Underhood

G	F	P	
☒	☐	☐	122. Engine Oil
☒	☐	☐	123. Brake Fluid
☐	☐	☒	124. Coolant - Low
☒	☐	☐	125. Power Steering Fluid
☒	☐	☐	126. Transmission Fluid
☐	☐	☒	127. Washer Fluid
☒	☐	☐	128. Transfer Case Fluid
☐	☒	☐	129. Engine Mounts
☒	☐	☐	130. Overall Engine Condition
☐	☒	☐	131. Engine Belts - Needs replaced
☒	☐	☐	132. Engine Hoses/Lines/Fittings
☒	☐	☐	133. Radiator
☒	☐	☐	134. Water Pump
☒	☐	☐	135. Coolant Recovery Tank
☐	☒	☐	136. Coolant Fans/Clutches/Motors - Bad fan motor
☒	☐	☐	137. Coolant Hoses
☐	☒	☐	138. Wiring - Loose
☒	☐	☐	139. Starter Operation
☐	☒	☐	140. Ignition Operation
☒	☐	☐	141. Battery
☒	☐	☐	142. Alternator
☒	☐	☐	143. Air Filter
☐	☒	☐	144. Fuel Filter - Dirty
☒	☐	☐	145. Fuel Pump
☒	☐	☐	146. Fuel System Operation

Road Test

G	F	P	
☒	☐	☐	147. Starting
☒	☐	☐	148. Idling
☒	☐	☐	149. Engine Noise
☒	☐	☐	150. Throttle
☐	☐	☒	151. Transmission Shift - Delay when engaging a gear
☒	☐	☐	152. Clutch Operation
☒	☐	☐	153. Accelerating
☐	☒	☐	154. Steering Alignment - Possible alignment problem
☒	☐	☐	155. Power Steering
☐	☒	☐	156. Cruise Control - Faulty fuse
☒	☐	☐	157. Braking
☒	☐	☐	158. ABS (Anti-Lock Braking System)
☒	☐	☐	159. Body/Suspension
☒	☐	☐	160. Interior Noise Level

Additional Notes

161. Additional Notes: - Lorem ipsum dolor sit amet, consectetur adipiscing elit.

Summary

Poor

Interior

Tilt/Telescoping Steering Wheel - Suspendisse scelerisque velit ac ligula gravida, ac interdum nisi vehicula.

Lighter/Power Outlet(s) - Not functional

Exterior

Parking Lights - Broken lens

Underbody

Overall Underbody Condition - Rust present

Catalytic Converter -

Rotors/Drums -

Underhood

Coolant - Low

Washer Fluid -

Road Test

Transmission Shift - Delay when engaging a gear